

Household recalls

The U.S. Consumer Product Safety Commission (CPSC) is responsible for ensuring that the items in our homes are safe. This document contains a list of recalls that I'm aware of, but it might not be complete as of the date you read it. Therefore, if you have a concern about an item, search the [CPSC web site](#) itself to check on the status of that item. You can also search on other items and subscribe to the CPSC email notification system by following the instructions [in this document](#).

Alarms (carbon monoxide, fire, and smoke alarms)

[Maple Chase Co. Recalls Carbon Monoxide and Carbon Monoxide/Smoke Combo Alarms Due to Alarm Malfunction \(May 15, 2008\)](#)

[Digital Security Controls Recalls Smoke Detectors that Could Fail to Warn of a Fire \(March 22, 2007\)](#)

[Gamewell-FCI Recalls to Upgrade Software Used with Fire Alarm System Control Boards \(January 31, 2007\)](#)

[Tyco Fire & Security Recall to Upgrade Software of Fire Detection Systems \(May 19, 2006\)](#)

[First Alert Smoke Alarms and Combination Smoke/CO Alarms Recalled for Rapidly Draining Battery Power \(May 2, 2006\)](#)

[GE Security Inc. Retrofit/Recall of Smoke Detector Systems \(December 22, 2004\)](#)

[GE Security Recall of Carbon Monoxide Alarms \(February 12, 2004\)](#)

[GE Interlogix Recall of Smoke Detectors \(September 3, 2003\)](#)

[Fire-Lite Alarms Recall of Power Supply for Alarm Systems \(March 11, 2003\)](#)

[Invensys Building Systems Announce Recall of Siebe Actuators in Building Fire/Smoke Dampers \(October 2, 2002\)](#)

[CPSC Recommends Carbon Monoxide Alarm for Every Home \(January 18, 2001\)](#)

[Smoke Alarms Recalled by Universal Security Instruments \(May 25, 2000\)](#)

[Interstate Engineering Announce Recall of Heat Detectors \(April 8, 1999\)](#)

[Carbon Monoxide Alarms Recalled by Kidde Safety \(March 19, 1999\)](#)

[Chemetronics Caribe Inc. Announce Recall of Heat Detectors \(July 28, 1997\)](#)

[Home Gas Sentry Carbon Monoxide Detectors Hazard \(August 6, 1996\)](#)

[CPSC Warns Of Failures With Sinostone Carbon Monoxide Detectors \(January 19, 1996\)](#)

[Moose Brand Control Panel Recalled by Sentrol, Inc. \(December 21, 1995\)](#)

["Gas Sniffer" Carbon Monoxide Detector Recalled by Revco \(November 22, 1995\)](#)

[Defective Alarm Prompts Recall Of Battery Powered Smoke Detectors \(December 18, 1992\)](#)

[Smoke Detectors Recalled by BRK \(September 4, 1992\)](#)

[Smoke Alarms Recalled by ESL \(November 1, 1983\)](#)

[Smoke Detectors Recalled By Honeywell \(May 24, 1983\)](#)

[Smoke Detectors Recalled by Chloride Pyrotector \(August 3, 1981\)](#)

[Smoke Detectors Recalled by BRK Electronics \(November 6, 1978\)](#)

[Smoke Detectors Recalled by BRK Electronics \(August 1, 1977\)](#)

[Smoke alarms Recalled by Master Lock \(July 29, 1977\)](#)

Dampers

[Invensys Building Systems Recall of Siebe Actuators in Building Fire/Smoke Dampers \(October 2, 2002\)](#)

[Air Damper Systems Repaired by Chim-A-Lator \(November 6, 1979\)](#)

Decks

[Royal Outdoor Products Announce Recall of Colonial Vinyl Deck Post Kits \(July 17, 2002\)](#)

**REAL ESTATE
SOLUTIONS**

provided by



San Diego, California

619.341.0173

RusselRayPC@aol.com



www.abouthomes.info